


FIG. 1






FIG. 2

FIG. 3





FIG. 4

CERTIFICATE OF DESTRUCTION


1 Date of Destruction May 12, 2004, at 3:00 pm

2 Picture of destroyed hard disk

Overall view



Enlargement of
manufacturing number portion



3 Worker

Name

OO OO

Picture



4 Place of destruction Kobe plant

5 Apparatus employed for destruction Second machine

6 Reason for destruction because ***

FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9A




FIG. 9B




FIG.10




FIG. 11




FIG. 12




FIG. 13A




FIG. 13B




FIG. 14A




FIG. 14B




FIG. 15




FIG. 16

CERTIFICATE OF DESTRUCTION	
ABC corporation	
1.	Date of destruction February 1, 2005, at 2:00 pm
2.	ID code of destroyed recording medium 17-2-1-0052
3.	Image data of destroyed recording medium stored in attached CD
4.	Destruction worker OO OO
5.	Place of destruction ABC plant
6.	Apparatus employed for destruction second machine HA-4000

FIG. 17





FIG. 18







FIG. 19

FIG. 20






FIG. 21

FIG. 22

FIG. 23





FIG. 24






FIG. 25




FIG. 26

FIG. 27A




FIG. 27B

